



# Sanitary Sewer Overflow 5-Day Follow Up Report

Division of Surface Water

**Report Submitted By**

Date:	6/9/2015
Facility name:	Gary L. Kron WRF
Ohio NPDES permit no.:	3PK00033*MD
Period covered by report:	6/8/2015
Contact person	
Name:	Micheal McGlothin
Title:	Superintendent
Mailing address:	8471 Lakeshore Blvd. Mentor, Ohio
County:	Lake
Telephone:	(440)350 - 3431
Email:	Micheal.mcglathin@lakecountyohio.gov

**Signature required at end of form****Overflow Information**

Event start date and time – if multiple locations, include information for each	6/8/2015 9:50am
Event end date and time	6/8/2015 10:45am
Location(s) the SSO – include unique ID number of one exists	Glyco I Lift Station Force Main air release vault. Fairport Nursury Road Painesville Twp., Ohio.
Destination(s) of overflow	<input type="checkbox"/> Basement or building <input checked="" type="checkbox"/> Ground <input type="checkbox"/> Storm sewer to receiving water <input type="checkbox"/> Directly to receiving water
Estimated volume (million gallons) - if multiple locations, include volume for each	.001
Sewer system component(s) from which release occurred	<input type="checkbox"/> Manhole <input type="checkbox"/> Constructed overflow <input type="checkbox"/> Pipe crack <input type="checkbox"/> Pump station <input checked="" type="checkbox"/> Other (explain) Lift Station vault
Cause(s) of overflow	<input type="checkbox"/> Extreme weather <input checked="" type="checkbox"/> Equipment failure <input type="checkbox"/> Power failure <input type="checkbox"/> Debris in line <input type="checkbox"/> Roots <input type="checkbox"/> Grease <input type="checkbox"/> Other blockages <input type="checkbox"/> Line deterioration <input type="checkbox"/> Vandalism <input type="checkbox"/> Other (explain)